

Tech Tips (00258)

MB Ignition Voltage Transformer R&R ONLY

000 150 0258 ProgRama # 00258

THIS UNIT FITS ONLY: 12 cylinder models

S600, CL600 2001 – 2013

SL 600, SL 65 AMG, CL 65 AMG 2004 -2011

MAYBACH 57S, 62S 2005 – 2011


Prior to installation of the Control Unit:

Check coil packs prior to replacing the unit as ignition transformer failure is a result of Coil failure. Check valve cover oil leakage. Excessive oil in the spark plug hole may cause premature coil and transformer failure.

000 150 0258 ProgRama # 00258
000 150 0158
000 150 0058


List price: \$368.75
R&R price: \$295.00
Core charge: \$ N/A
Core price: \$ N/A

Unit location (under the hood on top of the engine)






MB CL600 2003-2013



MB SL600 2003-2013



MB SL65AMG 2005-2011



MB S600 2003-2013

