Instructions (01103)

THIS UNIT REPLACES ONLY:			
107 series: all 1982 -1989			
123 series:			
280CE	1981 SERIAL NUMBERS GREATER THAN 022583		
280E	1981 SERIAL NUMBERS GREATER THAN 086881		
300CD	1981 SERIAL NUMBERS GREATER THAN 007198		
300CD	TURBO DIESEL 1982 - 1985		
300D	1981 SERIAL NUMBERS GREATER THAN 229986		
300D	TURBO DIESEL 1982 - 1985		
300TD	TURBO DIESEL WAGON 1981 SERIAL NUMBERS GREATER THAN 022342		
300TD	TURBO DIESEL WAGON 1982 - 1985 SERIAL NUMBERS GREATER THAN 002726		
126 series: all 1982 - 1985 SERIAL NUMBERS GREATER THAN 009981			
300SD	TURBO DIESEL 1982 - 1985 SERIAL NUMBERS GREATER THAN 005070		
300SD	81 ONLY SERIAL NUMBER LESS THAN 005069		

Perform steps 1 - 2 prior to installation.

- 1. Turn off ignition.
- 2. Disconnect connector from blower control unit. Red lead to battery voltage, black lead to pin 6. Current draw = less than 9 amps; IF NOT, REPLACE BLOWER MOTOR OR WARRANTY IS VOID.

ProgRama needs your experience and inputs to make a better product. Phone or email tech support today 8:30 am to 5:00 pm EST, with your idea, question or problem.

1 800 668-8843



THREE YEAR WARRANTY

1- Call your Wholesale Distributor for a replacement part.

2- If you have difficulties to obtain a replacement, call ProgRama, Inc. We offer up to 48 hrs. turn-around time for bench testing service.

3- Visit our web site www.programainc.com and become familiar with our products and services.

Warning ! Return Core In ProgRama Box for Proper Core-Deposit Refund

Blower Control Unit. Revised 01/05/02 #01103

GENERAL TROUBLESHOOTING NOTES

ORIGINAL UNIT PROBLEM

SymptomsTest/Suspect Problems Solution				
No fan	Faulty Blower motor. Isolate and check current draw. Current must be less than 9 amps	Replace Blower motor. Replace Blower Control Unit.		

NEW UNIT PROBLEMS

Symptom Test/Suspect Problem Solution

No automatic fan speed control.	Faulty Temperature Control Regulator.	Replace as needed.
---------------------------------	---------------------------------------	--------------------

Warning ! Return Core In ProgRama Box for Proper Core-Deposit Refund



Thank you for buying a quality part from ProgRama, Inc of Boca Raton, Florida !

Blower Control Unit. Revised 01/05/02 #01103