

(51232) Instructions

THIS UNIT FITS ONLY:

450SL	76 - 78	300CD	78 - 81
450SLC	76 - 78	300D	77 - 81
230	77 - 78	300TD	79 - 80
240	77 - 81		
280CE	77 - 81		

Perform this step prior to installation.

1. Insure cable on actuator moves freely. For the unit to work correctly there must not be any restriction on this cable.

TROUBLESHOOTING NOTES

ORIGINAL UNIT PROBLEM

Symptoms	Test/Suspect Problems	Solution
Unit will not engage.	Faulty cruise control amplifier.	Replace amplifier.

NEW UNIT PROBLEMS

Symptom	Test/Suspect Problem	Solution
Cruise Control will not engage.	No power at pin 5.	Check and rep
	Poor connection between pins and connector on Cruise Control Amplifier.	Check, clean and crimp connectors as needed.
	No ground at pin 12.	Check and repair as needed..
	Faulty vehicle Speed Sensor.	Check and repair.
Cruise Control will disengage or acts erratic. Vehicle surges or slows down and speeds up.	Vacuum leak	Check vacuum applied to acuator.

THREE YEAR WARRANTY