

Instructions (101)

THIS UNIT FITS ONLY:

M3	12/86 to 12/90	318i	03/90 to 04/91	318ic	07/90 to 12/92
325	01/86 to 07/88	325e	01/86 to 07/88	325es	01/86 to 09/86
325i	10/86 to 12/92	325iX	07/86 to 01/91		

Prior to installation, verify this is the correct part for your application.

- Remove light bar from old unit and place in ProgRama unit.**
- For correct operation, unit must be reset after installation.**

GENERAL TROUBLESHOOTING NOTES

NEW UNIT PROBLEM

Symptoms	Test/Suspect Problems	Solution
Inspection light will not reset	Batteries are not turned on.	Move jumper to on position.
Tach and MPG not working or working improperly.	Batteries are not turned on.	Move jumper to on position.
	Cracked or corroded solder on conductor plate.	Replace conductor plate.
Tach, MPG and Temp not working. Inspection light flashing.	No code plug.	Plug in code plug.
	Bad code plug	Replace code plug.
Light board has missing lights.	Visual inspect for cracked or corroded solder.	Replace light board.
No green lights.	Light bar missing.	Remove light bar from old unit and install in new unit.
Instrument cluster is performing incorrectly.	Conductor plate visual inspection for cracked or corroded solder.	Replace conductor plate.
Brake light stays on.	Faulty conductor plate.	Replace conductor plate.